


PC STA	421+34.61	PT STA	424+46.39
Δ	27° 02' 21"	Δ	27° 02' 21"
D	171.21	D	171.21
L	446.60	L	446.60
E	388.91	E	388.91
PC STA	418+34.07	PT STA	421+34.61
Δ	4° 32' 00"	Δ	4° 32' 00"
D	171.21	D	171.21
L	446.60	L	446.60
E	388.91	E	388.91
PC STA	415+34.07	PT STA	418+34.07
Δ	4° 32' 00"	Δ	4° 32' 00"
D	171.21	D	171.21
L	446.60	L	446.60
E	388.91	E	388.91

PC STA	424+46.39	PT STA	427+58.17
Δ	27° 02' 21"	Δ	27° 02' 21"
D	171.21	D	171.21
L	446.60	L	446.60
E	388.91	E	388.91
PC STA	421+34.61	PT STA	424+46.39
Δ	4° 32' 00"	Δ	4° 32' 00"
D	171.21	D	171.21
L	446.60	L	446.60
E	388.91	E	388.91
PC STA	418+34.07	PT STA	421+34.61
Δ	4° 32' 00"	Δ	4° 32' 00"
D	171.21	D	171.21
L	446.60	L	446.60
E	388.91	E	388.91



**I-4 EB to I-95 NB/SB Closed 10/22 – 10/24
take Beville Road to Williamson Boulevard**

**SB I-95 Closed From
ISB to S.R. 421 (10/25)
Take ISB east to
Williamson Boulevard
South to S.R. 421 or
ISB west to I-4**

**NB I-95 Closed From
Beville Road to ISB 10/25
Take Beville Road to
Williamson Boulevard
North**

I-95 SB

I-95 NB

ISB

Beville Rd

I-4

[Grey Hatching]	FILLING AND RESURFACING
[Dark Grey Hatching]	EXISTING AND NEW CONSTRUCTION
[Cyan Hatching]	POND
[Yellow Hatching]	BERRY